
## **Bathroom: Moldy Shower head**








# **Bathroom: Shower and Bathroom in poor condition**





Confidential

# **Lounge Sofa: Heavily Stained**



# **Lounge Sofa: Broken**




# **Dining Chairs: Cushions Heavil Stained.**





# **Carpets throughout Heavily Stained**





# **Damage to walls throughout**

